

Issue 1 dated June 2003 (AM5/03)

## Page 5

### 2.1 Traincrew's immediate actions

#### a) Driver's actions

##### **Explanation of change**

This amendment recognises that not all trains are fitted with the hazard warning indication.

Section 2.1 a) is amended to read as follows:

Issue 1 dated June 2003 (AM5/03)

## Page 5

### 2.1 Traincrew's immediate actions

#### a) Driver's actions

You must **immediately**:

- switch on the hazard warning indication (flashing headlights) where provided, and
- display a red light forward.

You must then check:

- the exact location of the train, and
- if any other lines are obstructed (if in doubt, treat them as obstructed), and decide the quickest way to stop any approaching trains.

driver